

VFI®-6070 70 D SPRAY HARD COAT

VFI-6070 70 D Spray Hard Coat is a 100% solids, polyurethane coating. It is capable of being sprayed through high or low-pressure equipment over CNC or hot wire cut EPS to create a protective, uniform surface for sanding, priming, and painting. While the hard coat is easily sandable, it does not always require post-work because its chemical makeup creates an extremely smooth finish. Spraying VFI-6070 allows you to create a variety of shapes for various theming applications, including props, sets, signs, museum displays, and more.

- Great for outdoor applications that need to withstand the elements
- Flat, glass-like texture with reduced need for sanding
- Cures to handle in 5 minutes for faster turnaround to complete a piece
- Saves time with spray application as opposed to brushable coatings

PHYSICAL PROPERTIES	TEST METHOD	TEST RESULTS
Shore Hardness	ASTM D2240	70 D
Tensile Strength	ASTM D412	3,600 psi
Tensile Modulus	ASTM D638	240,000 psi
Elongation	ASTM D412	8%
Flexural Strength	ASTM D790	8,700 psi
Flexural Modulus	ASTM D790	230,000 psi
Abrasion Resistance	ASTM D4060	N/A
Impact Resistance (Notched)	ASTM D256-10	.605 ft·lb
Weathering	N/A	Not UV Stable
Linear Shrinkage	N/A	N/A
Heat Deflection Temperature	ASTM D648	N/A
Color	N/A	Neutral
Class A Fire Testing	ASTM E84	No

LIQUID PROPERTIES	TEST METHOD	TEST RESULTS
Solids by Volume	ASTM D2697	100%
Mix Ratio by Volume	N/A	1A:1B
Weight per Gallon A Side	ASTM D1475	9.78 lb/gal
Weight per Gallon B Side	ASTM D1475	8.65 lb/gal
Viscosity A Side	ASTM D2196	500 cps
Viscosity B Side	ASTM D2196	1,200 cps
Gel Time	N/A	N/A
Tack Free Time	N/A	80 seconds
Cure to Handle	N/A	5-7 minutes
Recoat Window	N/A	20 minutes
Full Cure Time	N/A	3 days
Volatile Organic Compounds	N/A	0

MANUFACTURER OF HIGH-PERFORMANCE POLYMERS
Toll-Free 800-307-9218 | www.volatilefree.com | info@volatilefree.com

This information and technical advice provided herein are believed to be reliable and accurate to the best knowledge of Volatile Free, Inc., As based on tests and should serve only as a recommendation. As the manufacturer, Volatile Free, Inc makes no representations or warranties of any kind, expressed, implied or statutory, including but not limited to all implied warranties of merchantability or fitness for use or a particular purpose, or any other matter with respect to this product. Volatile Free, Inc makes no representations or warranties as to the results of the use of the product and assumes no obligation or liability in connection therewith. Volatile Free, Inc is not liable for any special, exemplary, punitive, incidental or consequential damages of any sort or kind from use of this product. The information provided herein is subject to change at any time without notice. Information changes may include, but are not limited to, commercial and technical changes, changes in pricing, physical characteristics and packaging.

VFI®-6070 70 D SPRAY HARD COAT

THICKNESS REQUIREMENTS

We recommend spraying at a minimum rate of 60 mils or greater to create the best film properties. If subsequent coats are needed, you must stay within the 20-minute open window. If you exceed the open window, we recommend using a primer to create adhesion between layers.

EQUIPMENT

Low Pressure - VFI-6070 requires a low-pressure machine capable of spraying through a static mix tip. The machine needs to have enough pressure to fully clear the tip in 20 seconds, or the material will set up in the static mix tip. Heating the lines and material is recommended for optimal spray pattern and properties but is not required. The recommended temperature for heating the lines and material is between 80°F-100°F.

High Pressure - A high-pressure, plural component machine capable of heating the product and providing a minimum 2500 PSI of constant pressure can also be used. The recommended settings are constant pressure between 2300-2500 PSI and temperature between 150-155°F.

SURFACE PREPARATION

- **EPS** - Ensure that the EPS has been aged at least 30 days. Anything between 1 and 3 PCF is acceptable, but for an optimal cost-to-quality ratio, we recommend using 2 PCF foam. Once clean and dry, the coating can be applied directly to the EPS.
- **Wood** - The wood should be dry and contain less than 11% moisture; otherwise, it should be primed or mist-coated (a light dusting of the coating followed by the main application of the coating).
- **Urethane or Plastic** - First, sand the urethane or plastic and then apply a general urethane primer to ensure good adhesion to the substrate.

MIXING

The B side (Poly) must be premixed until uniform before use and continuously mixed throughout the application. The A side (Iso) does not need to be mixed. Mix times will increase if stored for long periods between use.

APPLICATION & CLEANUP

The material will need at least 3 hours to cure before heavy movement is allowed, but it is sandable within an hour. Light movement is acceptable sooner than 3 hours if needed. If spraying in thinner passes, it may require a longer post-cure time. The preferred cleanup solvent is xylene or MEK. For cleaning and flushing out lines, VFI recommends using the VFI-8005 Pump Flush to fully clean out the lines.

CROSS CONTAMINATION

VFI-6070 should be able to run behind most polyureas and polyurethanes without issue, but VFI always recommends a test mix on the side before use. The test mix can be taken by combining some of the new material with some material within the spray lines and mixing them to see if there's a reaction.

STORAGE/SHELF LIFE

The shelf life of unopened containers is 12 months after the date of manufacture. Store the product between 60°F - 90°F in a clean, dry building. Once opened, use immediately. After opening, it is possible to store unused products by nitrogen purging both sides immediately after use. If you don't nitrogen purge the material, moisture contamination can occur in the A & B sides. The moisture contamination will create a hardened film over and in the A side (Iso) and can cause pinholes and foaming in the B side (Poly) when spraying. We recommend using VFI-8403 Dryer to reduce the moisture contamination effects in the B side.

PRECAUTIONS

See the Safety Data Sheet for all information regarding safety.